

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	30051	(detect\$3 or sens\$3 or monitor\$3) near3 (gas or air) near4 (flow\$3 or circulat\$3 or vent\$3)	USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/19 13:47
L2	277315	(gas or air) near5 (vent\$3 or enclos\$4 or duct\$3)	USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/19 13:48
L3	1275	1 and 2 and (alarm\$3 or alert\$3 or warn\$3)	USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/19 13:48
L4	74553	(verification or user or operator or control\$4) near3 (alarm\$3 or warn\$3 or alert\$3)	USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/19 14:12
L5	4139	4 near5 (input\$4 or enter\$3 or adjust\$3 or increas\$3 or decreas\$3)	USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/19 13:50
L6	32	3 and 5	USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/19 13:59
L8	2	6 and ((set\$4 or adjust\$3 or input\$4 or output\$4) near7 overrid\$3)	USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/19 14:13
L9	3	1 and 5 and ((set\$4 or adjust\$3 or input\$4 or output\$4) near7 overrid\$3)	USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/19 14:08
L10	18	6 and (different\$4 near2 pressure)	USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/19 14:18
L11	3	6 and damp\$3 and restric\$3	USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/19 14:18
L12	5655	(verification or test\$3 or verifying) near4 (alarm\$3 or warn\$3 or alert\$3)	USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/19 14:13
L13	3	3 and 12 and ((set\$4 or adjust\$3 or input\$4 or output\$4) near7 overrid\$3)	USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/19 14:14
L14	0	13-and-(different\$4-near2-pressure)	USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/19 14:18
L15	0	13 and damp\$3 and restric\$3	USPAT; EPO; JPO; DERWENT	OR	ON	2004/11/19 14:18